GOVERNMENT OF ANDHRA PRADESH A B S T R A C T

Public services- Irrigation & CAD Department – Sri M. Satyam Naidu, Assistant Engineer formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram - Negligence in performing duties- - Departmental Proceedings under Rule 20 of the A.P.C.S. (CC & A) Rules, 1991-Article of charges- Issued.

IRRIGATION & CAD (SER.X.2) DEPARTMENT

G.O.Rt. No. 1241 DT: 12.09.2008

ORDER:

It is proposed to hold an enquiry against Sri M. Satyam Naidu, Assistant Engineer, formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram in accordance with the procedure laid down in Rule 20 of the A.P.C.S. (CC & A) Rules, 1991.

- 2. The substance of the imputations of misconduct or misbehavior in respect of which the inquiry proposed to be held is set out in the enclosed statement of Articles of charges (Annexure-I) ,statement of imputations of misconduct and misbehavior (Annexure-II),a list of documents by which and a list of witnesses by whom, the article of charges are proposed to be sustained are also enclosed (Annexure III & IV)
- 3. Sri M. Satyam Naidu, Assistant Engineer formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram is directed to submit his explanation within 10 days from the date of receipt of these orders and submit a Written Statement of Defence and state whether he wants to be heard in person.
- 4. Sri M. Satyam Naidu, Assistant Engineer formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram is informed that an inquiry will be held only in respect of those articles of charges which are not admitted. He should, therefore, specifically admit or deny each article of charge.
- 5. Sri M. Satyam Naidu, Assistant Engineer formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram is further informed that if he does not submit his Written Statement of defence on or before the date specified in para 3 above, further action will be processed basing on the material available.
- 6. Attention of Sri M. Satyam Naidu, Assistant Engineer formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram is invited to Rule 24 of the A.P.Civil Services (Conduct) Rules, 1964 under which no Government servant shall bring or attempt to bring any political or outside influence to bear upon any superior authority to take further his interest in respect of matters pertaining to his service under the Government., if any representation is received on his behalf from another person in respect of any matter, it will be dealt within in these proceedings.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

K.S.P.V. PAVAN KUMAR JOINT SECRETARY TO GOVERNMENT

То

Sri M. Satyam Naidu, Assistant Engineer, formerly worked in R.M.C Section Kurupam of Irrigation Sub-division, Parvathipuram through the Engineer-in Chief, (Administration Wing) Hyderabad.

Copy to the Engineer-In-Chief (Admn. Wing) I&CAD Department, Hyderabad

//FORWARDED : : BY ORDER//

ANNEXURE-I

<u>Draft articles of charges framed against Sri M. Satyam Naidu, Assistant Engineer formerly worked in RMC Section Kurupam</u>

Sri M. Satyam Naidu Assistant Engineer, has committed dereliction of duties amounting to misconduct in violation Rule 3 of APCS (Conduct) rules, 1964 as mentioned in the following articles of charges:

<u>Articles of Charge-1</u>: That the said Sri M. Satyam Naidu while functioning as Assistant Engineer in RMC Section, Kurupam was responsible for the execution of following works in Jiyyammavalasa (M) during 1998-99.

- i. Restoration of Gowrisagaram Tank of Gowrampeta village and
- ii. Restoration of Jagannadha Sagaram tank of Parajapadu (V)

During the execution of these works he has failed to maintain the required Quality control registers for obtaining the Quality control certificates for the work done, which resulted in non-payment of final bills to the President of the water users Associations concerned. Consequently the president of the W.U.A. filed a complaint No. 42/2006 for settlement of bills, which is an un-warranted litigation thrust on the Department for which Sri M. Satyam Naidu is responsible.

S.P.TUCKER
PRINCIPAL SECRETARY TO GOVERNMENT

//FORWARDED : : BY ORDER//

ANNEXURE-II

STATEMENT OF IMUTATIONS OF MISCONDUCT OR MISBEHAVIOUR IN SUPORT OF THE ARTICLES OF CHARGES FRAMED AGAINST SRI M. SATYAM NAIDU, ASSISTANT ENGINEER FORMERLY WORKED IN R.M.C SECTIN KURUPAM

Sri M. Satyam Naidu, Assistant Engineer has worked in R.M.C. section, Kurupam of irrigation Sub-Division, Kurpam of Irrigation Division, Parvathipuram from 27.05.1999 to 6.6.2003. During his incumbency he has executed the work for restoration of Gowrisagaram tank of Gowrampeta village. He has also recorded measurements for the said work in M.Book No.7 Chinnamarangi on 9.6.1999, 26.6.1999, 28.7.1999, 6.9.1999, 6.7.2000 and 11.7.2001 at P.No.1 to 11 and in M.Books check measured on 6.7.2001 and 11.7.2001 at 25 to 28 and got check measured by Sri G. Rama Mohana Rao the then Deputy Executive Engineer and Sri K.Sanyasi Rao, the then Executive Engineer now retired. The Asst. Engineer has taken final levels and recorded in L.F. book No.1/98-99. But the Assistant Engineer has not maintained the required Quality Control Register and not got test check measured the pre and final levels by the Quality control authorities.

The Assistant Engineer has also executed the work in RMS Section Kurpam for Restoration of Jagannadhasagaram Tank of Parajapadu (V) in Jiyyammavalasa Mandal during 1998-1999 for Est. Rs. 16.00 lakhs under Cr.No.27/98-99. through Sri G Appala Naidu President W.U.A. of Kudamba (V)) vide Agt. No21-SE/98-99. The Assistant Engineer has recorded the measurements for the above work in M. Book No. 10 K at P.No.1 to 7 and in M. Book No. 11 K at P.No.1 to 10 on 5.6.99, 5.7.99, 29.7.99, 14.8.99 and 2.7.2000 respectively and got check measured by Sri G Rama Mohana Rao the then Deputy Executive Engineer and Sri K. Sanyasi Rao the then Executive Engineer (now retired). The Assistant Engineer has also taken prelevels and final levels and recorded in L.F. Book No.1K Kudam (V). But the levels were not got test checked by the Quality Control authorities.

Because of failure in maintaining the statutory Register by Assistant Engineer the quality control authorities have denied to issue Quality Control certificate, which resulted in non-payment of final bills to W.U.A. President and led to judicial scrutiny thrust upon the department.

Thus the department has to face an embarrassing situation. This shows the mis-conduct and mis-behavior of the Assistant Engineer in discharging his official duties.

S.P.TUCKER
PRINCIPAL SECRETARY TO GOVERNMENT

//FORWARDED : : BY ORDER//

ANNEXURE-III

List of Documents:

- 1. M. Book No. 6 CHM No. and 7 CHM
- 2. L.F. Book No.3/98-99 and 1/98-99
- 3. M. Book No.10 K and 11 K
- 4. L.F. Book No. 2 Kudama
- 5. AP. Lokayukta orders dt. 19.10.2006 in complaint No. 42/2006

S.P.TUCKER PRINCIPAL SECRETARY TO GOVERNMENT

//FORWARDED : : BY ORDER//

SECTION OFFICER

ANNEXURE-IV List of witnesses: NIL

> S.P.TUCKER PRINCIPAL SECRETARY TO GOVERNMENT

//FORWARDED : : BY ORDER//